UR CRITICAL E	SRIDGE - PLA	IN OF ACTION	
tructure ID Number (5A01): District, County, Location and Owner (5A04);(5A05);(5A06);(5A21): 09; 55 - Somerset; 55/424 - INDIAN LAKE; 04 -City/Muni Hwy Agency			
Facility Carried (5A08): PENINSULA DRIVE		Feature Intersected (5A07): CALENDARS RUN	
Rebuilt (5A16): 0 Structure Type (6A26-29): 1993		A26-29): 19934 ST PIPE	CULV
B14) = 0 ; Main = (5B1	1) 4		
Bridge ADTT (6C27): -1		ADT Year (5C11): 2009	
Channel (1A05): 6		Waterway Adequacy (1A06): 7	
2. Scour Information			
BI Code (IU03): O	Minimum Obs. Scou	r Rating (IN03): 6	SCBI Category: C
oundation IN03 Type Observed	ig		
6	Minor settlement causing small voids between pipes and toewalls. No scour or undermining.		
6	Minor settlement causing small voids between pipes and toewalls. No scour or undermining.		
C bridge here.)			
Note: Slight chance of overtopping bridge deck and roadway approaches			
ed below is to be insta pletion of these mainte	lled in accordance v nance items should	with a schedule consisten protect the bridge from fu	t with the Phonty irther scour damage
IMOS	IMOS Data	IM07 Status	IM08 Target
Priority	Recomended		Year
		0 - Work not planned 0 - Work not planned	0 2009
r structure			
Bridge in Pressure Flow Severe Debris accumulation			
Movement of riprap/other armor protection			
nkment			
(6A06): 424			
		DOT	ad Bridge Cofeby
ge: After scour inspecti pproval by the bridge o	on performed by a F owner.	PennDOT qualified Certifi	ed Bridge Salety
s are being submitted v	with this POA:	u balaa uudamainina dab	rie atc
□ Attachment B: Cross sections from current and previous inspection reports which includes substructure			
p showing detour route((s) (Optional)		•
	District, County, Loca 09; 55 - Somerset; 5 Facility Carried (5A08 PENINSULA DRIVE Rebuilt (5A16): 0 314) = 0; Main = (5B1 Bridge ADTT (6C: Channel (1A05): 0 Observed Scour Ratio 6 C bridge here.) ing bridge deck and ro ed below is to be instabletion of these mainte IM05 Priority 4 - Routine Structura 4 - Routine Structura 4 - Routine Structura 6 resideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation Insideration of bridge con structure movement / settlement Flow Imulation of bridge con structure movement / settlement Flow Imulation of bridge con structure movement / settlement Flow Imulation of bridge con structure movement / settlement Flow Imulation of bridge con structure movement / settlement Flow Imulation of bridge con structure movement / settle	District, County, Location and Owner (5A 09; 55 - Somerset; 55/424 - INDIAN LAN 09; 55 - Somerset; 55/424 - INDIAN LAN Facility Carried (5A08): PENINSULA DRIVE Rebuilt (5A16): 0	Featility Carried (5A08): PENINSULA DRIVE Rebuilt (5A16): 0